

## ATTACHMENT 1

### **Request No. 1:**

Provide the date of the most recent reline for each furnace 4, 6, and 8. For each most recent furnace reline, provide narrative description of the changes made to the furnace, explaining the difference in refractory, controls or any other change that was not an exact replacement in kind. Provide the production from each furnace for the 4 years prior to the most recent reline and 4 years after the most recent reline, in tons of hot metal per hour.

### **U. S. Steel Response:**

#4 Blast Furnace Reline was performed during the 1<sup>st</sup> quarter 1990. The following tasks were performed during the reline. Repairs were either an exact replacement or an improved replacement in kind. Items that were not an exact replacement were projects to improve the cooling and refractories of the Blast Furnace to improve reliability, extend campaign life, and reduce require repairs during a reline. The use of alumina and SIC refractories as replacement refractory improved the protection, durability and reliability of the Blast Furnace

- a. A new graphite cooled carbon hearth with ceramic plug which provides better cooling to the hearth and re-brick the bosh area with SIC refractory. SIC refractory was used to achieve greater longevity of the refractories.
- b. Improvements to the bosh channel cooling system by increasing water velocities through the cooling system which improve the longevity of the bosh.
- c. Increase the cooling plate density in the lower stack; add cooling plates in the upper stack region to increase hear removal.
- d. Rebrick the stack with high alumina refractory and SIC in the lower stack region.
- e. Replace shell plates in kind as required and provide access for remote control gunning device.
- f. Installation of a back draft stack to reduce wear on stoves. Back drafting the furnace occurred through the stoves prior to the installation of the back draft stack.
- g. Repair of the existing gas system and gas cleaning system.
- h. Stove inspection and repair in kind.
- i. Remove and rehabilitate top machinery.
- j. Stockhouse inspected and repaired in kind.
- k. Since reline outage was postponed for 1 year, the following items were added to the reline scope: Additional stack shell replacement, bustle pipe refractory and shell repair, skip bridge repair, offtake, uptake, and downcomer lining, replacement of coke vibrating feeders, additional stove checker replacement, and install swinging iron runner in the casthouse.

Production data in tons of hot metal per hour are not available. Listed below are the total tons produced for the four calendar years before and after the reline.

### **Units – tons / year, R – Reline Year**

1986	1987	1988	1989	1990(R)	1991	1992	1993	1994
348,000	585,000	953,912	660,930	1,039,507	1,325,123	1,308,218	1,155,200	1,205,295

#6 Blast Furnace Reline was performed during the 3<sup>rd</sup> quarter 1998. The following tasks were performed during the reline. Repairs were either an exact replacement or an improved replacement in kind. Items that were not an exact replacement were projects to improve the cooling and refractories of the Blast Furnace to improve reliability, extend campaign life, and


Table 12.5-1 (cont.).

Source	Units	Emission Factor	EMISSION FACTOR RATING	Particle Size Data
Blast furnace				
Slip	kg/Mg (lb/ton) slip	39.5 (87.0)	D	
Uncontrolled casthouse	kg/Mg (lb/ton) hot metal			
Roof monitor <sup>b</sup>		0.3 (0.6)	B	Yes
Furnace with local evacuation <sup>c</sup>		0.65 (1.3)	B	Yes
Taphole and trough only (not runners)		0.15 (0.3)	B	
Hot metal desulfurization	kg/Mg (lb/ton) hot metal			
Uncontrolled <sup>d</sup>		0.55 (1.09)	D	Yes
Controlled by baghouse		0.0045 (0.009)	D	Yes
Basic oxygen furnace (BOF)				
Top blown furnace melting and refining	kg/Mg (lb/ton) steel			
Uncontrolled		14.25 (28.5)	B	
Controlled by open hood venter to:				
ESP		0.065 (0.13)	A	
Scrubber		0.045 (0.09)	B	



United States Steel Corporation  
Law Department  
600 Grant Street  
Pittsburgh, PA 15219-2800  
Tel: 412.433.2919  
Fax: 412.433.2964  
E-mail: dwhacker@uss.com

David W. Hacker  
Attorney-Environmental



January 7, 2008

**VIA FEDERAL EXPRESS OVERNIGHT DELIVERY**

Attn: Compliance Tracker, AE-17J  
Air Enforcement and Compliance Assurance Branch  
U.S. Environmental Protection Agency  
Region 5  
77 West Jackson Boulevard  
Chicago, IL 60604

Dear U. S. EPA Region V Representative:

On or about November 9<sup>th</sup>, United States Steel Corporation (U. S. Steel) received a Clean Air Act Section 114 Request for Information. On December 7, 2007, U. S. Steel provided responses to the Request. As noted in our December 7, 2007 response and as indicated in the December 4, 2007, telephone conversation between David Hacker of U. S. Steel and Brian Dickens of U.S. EPA Region V, U. S. Steel indicated that it would supplement the response no later than January 8, 2008. This correspondence and attachments serve as that supplemental response. A certification page is provided immediately prior to the attachments.

Consistent with our prior responses, please note for organizational purposes, regardless of the length of the response, U. S. Steel's response to each inquiry is provided as a separate attachment so that the attachment number will correlate to the original request number.

1. Provide the date of the most recent reline for each furnace 4, 6, and 8. For each most recent furnace reline, provide narrative description of the changes made to the furnace, explaining the difference in refractory, controls or any other change that was not an exact replacement in kind. Provide the production from each furnace for the 4 years prior to the most recent reline and 4 years after the most recent reline, in tons of hot metal per hour.

*Please refer to the pages behind Tab No. 1 for U. S. Steel's response to this Request.*

2. Provide the emissions of hydrogen cyanide (HCN) from blast furnace operations for each blast furnace. Provide a narrative description of how U. S. Steel calculated or measured these emissions.

*Please refer to the pages behind Tab No. 2 for U. S. Steel's response to this Request.*

## ATTACHMENT 6

**Request No. 6:**

Provide the increase in emissions of sulfur dioxide from the blast furnace casthouse and all emission units that burn blast furnace gas as a result of Pulverized Coal Injection project. Provide a description of the methods U. S. Steel used to arrive at this emission increase.

**U. S. Steel Response:**

Changes to SO<sub>2</sub> emissions from Blast Furnace Casthouses as a result of Pulverized Coal Injection Project cannot be determined. Pre-Pulverized Coal Injection data does not exist for Casthouse SO<sub>2</sub> emissions. Therefore any increase or decrease to SO<sub>2</sub> emissions cannot be determined. Testing that was performed in March 2002 was located and the results are tabled below along with an explanation of SO<sub>2</sub> formation in Blast Furnace Casthouses at Gary Works.

The release mechanism for SO<sub>2</sub> during the casting operations is the release and subsequent oxidation (combustion) of hydrogen sulfide (H<sub>2</sub>S) gas emitted from hot metal and slag. The H<sub>2</sub>S gas is liberated from molten iron as it exits the tap hole, enters the iron trough, flows through iron runner and drops into torpedo cars. H<sub>2</sub>S is also released from slag as it exits the tap hole. The H<sub>2</sub>S released from the hot metal and slag is burned in the presence of oxygen to form SO<sub>2</sub> in air in regions where the air temperature is above the ignition temperature of H<sub>2</sub>S and the concentration of H<sub>2</sub>S are between the lower and upper flammability limits for H<sub>2</sub>S. In general, these conditions exist within a few inches above the molten metal or slag streams.

On March 11, 2002, stack test was conducted at the baghouse stack on #13 BF Casthouse. The results of the test are displayed in the table below.

Results of SO<sub>2</sub> Emission Testing

Run No.	Date	Time	Duration (min)	Casting Rate (tons/hr)	SO <sub>2</sub> Emission Rates	
					(lbs/hr)	(lbs/ton)
1	3/11/2002	0840-0940	60	323	137.7	0.519
2	3/11/2002	0941-1041	60	237	151.3	0.638
3	3/11/2002	1042-1142	60	194	79.2	0.408
4	3/11/2002	1143-1243	60	231	116.3	0.503
5	3/11/2002	1244-1400	76	341	40.1	0.117
<b>Mean</b>			<b>63</b>	<b>265</b>	<b>110.9</b>	<b>0.437</b>

The South Blast Furnaces (No. 4, 6, and 8) at Gary Works are equipped with iron oxide fume suppression systems for PM<sub>10</sub> emission control. These systems deprive the molten streams of oxygen, which suppress the formation of iron oxide fume. It is most reasonable to assume that the oxygen deprivation also suppresses the oxidation of H<sub>2</sub>S to SO<sub>2</sub>. There is no known practical and safe method of testing the emissions of SO<sub>2</sub> from the casthouse roof monitors at the south furnaces. SO<sub>2</sub> emissions from these casthouses are being estimated by conservatively assuming 50% suppression efficiency and assuming that the uncontrolled emission factor determined by the #13BF testing.

Changes to SO<sub>2</sub> emissions from all emission units that burn blast furnace gas as a result of Pulverized Coal Injection Project cannot be determined. Emission units that burn blast furnace gas are: stoves for Blast Furnaces 4, 6, 8, & 13/14, No. 4 Boiler House, and Turbo Blower Boilers